

REMARKS ONGOING RODENT ACITIVITY ON SOUTH END OF RWY.

LAND RWY 36, DEPART RWY 18, WITH A RIGHT TURN DOWN CROOKED CREEK.

LANDING OR TAKEOFF WITH UNFAVORABLE WINDS NOT RECOMMENDED. CHECK

AIRCRAFT PERFORMANCE FOR HIGH DENSITY ALTITUDE. RUNWAY MAY NOT BE VISIBLE

FROM ALL PARTS OF THE TRAFFIC PATTERN. STEEP ENCLOSING TERRAIN.

EXTENSIVE HELICOPTER ACTIVITY IN SUMMER MONTHS. NO WINTER MAINTENANCE.

RECOMMENDED FOR USE ONLY BY MOUNTAIN PROFICIENT PILOTS.

9-20

DIXIE USES

A05